ABSTRACT

Method for manufacturing complex shape parts including parts with cavities from powder materials by Hot Isostatic Pressing (HIP) with controlled pressure inside the HIP tooling and multi-layer inserts including hollow inserts. Controlled pressure inside the HIP tooling is provided by injecting the HIP gas media into the cavities of the hollow inserts.